😓 派 玆 SailWind Logic Quick Reference

Keyboard Shortcuts

Function Key Command Assignments			
Кеу	Description		
F1	Open Help (context sensitive)		
F2	Add connection		
		Editing	
Shortcut	Description		
End	Redraw		
Ctrl+D			
Keypad (1)			
Delete	Delete selected object		
Escape	Can	cel command	
		Selection	
Shortcut		Description	
Ctrl+Alt+F		Display the Selection Filter	
Click		Select an object	
Spacebar			
Ctrl+A		Select all items on current sheet (based on filter)	
Ctrl+Shift+A		Select all items on the schematic (based on filter)	
Click+Drag		Start an area selection	
Ctrl+Click		Toggle object selection or select multiple objects	
Ctrl+Click+D	Duplicate selected object and attach to pointer		
		Placement Operations	
Shortcut	De	escription	
Ctrl+E	M	ove the selected object(s)	
Ctrl+R	Rotate the selected object 90 degrees		
Ctrl+F	X Mirror (flips selected object on X axis)		
Ctrl+Shift+F	Y Mirror (flips selected object on Y axis)		
Ctrl+Shift+J	Vertically justify text during move		
Ctrl+J	Horizontally justify text during move		
Ctrl+Shift+O	Co	onnect to Layout for cross-probing	
		File Operations	
Shortcut	Des	scription	
Ctrl+N	Cre	ate a new design file (blank)	
Ctrl+O	Ope	en a design file	
Ctrl+P	Prir	nt/plot	
Ctrl+S	Sav	ve a design file	
		Viewing	
Shortcut	Des	scription	
Alt+N	Dis	play the next view	
Alt+P	Dis	play the previous view	
Mouse Button Substitutions			
	М	ouse Button Substitutions	
Shortcut	M Des	ouse Button Substitutions	

Panning, Zooming, and Navigation				
Shortcut	Description			
Home	Zoom to sheet. Fit the sheet border into the			
Keypad (7)	workspace.			
Ctrl+B				
Ctrl+Alt+E	Zoom to fit all objects in the design to the maximum of the viewable workspace			
Middle+Drag	Zoom from center. Drag up to zoom in.			
Keypad (5)	Drag down to zoom out.			
Shift+Middle+Drag	Zoom from corner. Drag up to zoom in.			
Keypad(.) (Zoom Mode only)				
Alt+Z	Zoom to fit the selectable object(s) to the maximum of the viewable workspace			
Ctrl+W	Toggle Zoom Mode on/off			
Click	Zoom in at the pointer (Zoom Mode)			
Page Up				
Space Bar				
Keypad(9)				
Right-Click	Zoom out at the pointer (Zoom Mode)			
Page Down				
Keypad(3)				
Page Up	Zoom in at the pointer			
Keypad(9)				
Ctrl+Wheel Fwd				
Page Down	Zoom out at the pointer			
Keypad(3)				
Ctrl+Wheel Back				
Down Arrow	Move the pointer down one design grid			
Up Arrow	Move the pointer up one design grid			
Left Arrow	Move the pointer left one design grid			
Right Arrow	Move the pointer right one design grid			
Middle-Click	Pan to center the view on the pointer			
Keypad(0)				
Insert				
Alt+Middle+Drag	Pan dynamically			
Wheel Back	Pan down one line			
Keypad (2)				
Wheel Fwd	Pad up one line			
Keypad (4)				
Shift+Wheel Back	Pan right one line			
Keypad (6)				
Shift+Wheel Fwd	Pan left one line			
Keypad (8)				
Ctrl+Alt+Wheel Back	Pan down one pixel			
Ctrl+alt+Wheel Fwd	Pan up one pixel			
Alt+Shift+Wheel Back	Pan right one pixel			
Alt+Shift+Wheel Fwd	Pan left one pixel			

Connection Operations		
Shortcut	Description	
Click	Add a new connection corner	
Space Bar		
Backspace	Remove the last routed corner on a connection line or the last corner on a 2D line (in polygon or path drawing mode)	
Enter	Complete the bus	
Double-Click		
Ctrl+L	Rename Connection/Change Part Type/Net Properties	
Ctrl+Page Down	Reset delta coordinates to measure from current position	
Ctrl+Space Bar	Add a ground symbol while in Add Connection mode	
Shift+Space Bar	Add a power symbol while in Add Connection mode	
Alt+Space Bar	Add an off-page symbol while in Add Connection mode	
Ctrl+Tab	Cycle through alternate gate symbols	

Opening Menus and Dialog Boxes		
Shortcut	Description	
Right-Click	Open the shortcut menu	
Ctrl+Alt+M	Toggle the visibility of the menu bar	
Double- Click	Open Properties dialog box for selected object	
Alt+Enter		
Ctrl+Q		
Ctrl+Enter	Open the Options dialog box	
Ctrl+Alt+C	Open the Display Colors dialog box	
Ctrl+Alt+S	Open the Status Window	
Μ	Opens the Modeless Command dialog box	

Modeless Commands

Grid Settings				
Command	Description			
G <n></n>	Set the Design grid, example G50			
GD <n></n>	Set the Displayed (Dot) grid, example GD100			
2D Line Angle Settings				
Command	Description			
AA	Any angle mode			
AD	Diagonal angle mode (45 degree angles only)			
AO	Orthogonal angle mode (90 degree angles only)			
Line Width Settings				
Command	Description			
R <n></n>	Set "Minimum display width" to <n>, example R 50. Widths less than <n> display as single pixel center lines</n></n>			
W <n></n>	Changes next line width to <n>, example W 5</n>			
Drafting Shape Control				
Command	Description			
НС	Set drawing mode to circle shape			
нн	Set drawing mode to path shape			
HP	Set drawing mode to polygon shape			
HR	Set drawing mode to rectangle shape			
	Hierarchical Design			
Command	Description			
н	Invoke Hierarchical Push			
НО	Invoke Hierarchical Pop			

Miscellaneous			
Command	Description		
?	Show the Help topic for Modeless Commands and keyboard shortcuts		
SH <sheet></sheet>	Select the sheet name or number you type, example SH3		
I	Run Database Integrity Test		
Search Commands			
Command	Description		
S <x> <y></y></x>	Search absolute at <x> <y>, for example S 1000 1000</y></x>		
S <s></s>	Search for named item (pin, part or net), example S U1		
SR <x> <y></y></x>	Search relative X and Y, for example SR -100 -50		
SRX <x></x>	Search relative X at current Y, for example SRX 300		
SRY <y></y>	Search relative Y at current X, for example SRY 400		
SX <x></x>	Search absolute X at current Y, for example SX 300		
SY <y></y>	Search absolute Y at current X, for example SY 400		
-	Measurement		
Command	Description		
Q	Quick Measure		
	Undo and Redo Operations		
Command	Description		
UN	Undo		
RE	Redo		